

Release Notes OpScan® Scanner Utilities

Thank you for purchasing the OpScan Scanner Utilities.

This document contains the following information:

- Scanners Supported with the OpScan Scanner Utilities
- CD Contents
- Installing the OpScan Scanner Utilities

If you have any questions about this product:

• Call Scantron Customer Support at 1-800-338-5544

Scanners Supported with the OpScan Scanner Utilities

- OpScan 2/4/4ES
- OpScan 6/8
- OpScan 10
- OpScan 15
- OpScan 16
- OpScan 21

CD Contents

Software included on the CD:

• Scanner utilities software for working with technical support

Documentation included on the CD (requires Adobe® Reader®):

• OpScan 4ES

- o OpScan 4ES and iNSIGHT 4ES Operator's Guide
- o OpScan 4ES and iNSIGHT 4ES Quick Start
- o OpScan 4ES and iNSIGHT 4ES Quick Tips Display Panel Messages
- o Scantron Scanners Elements of Data Collection
- o Select Stacker Operator's Guide
- SelfScore Operator's Guide
- SelfScore Quick Start
- o SelfScore Quick Tips Scanning Tests, Surveys, and Ballots

• OpScan 6/8

- o OpScan 6 Operator's Guide
- o OpScan 8 Operator's Guide
- o OpScan 8 Installation Guide

• OpScan 10/15/21

- o OpScan 10/15 Installation Guide
- Installing USB Adapter Software for Windows 7

• OpScan 16

- o OpScan 16 Operator's Guide
- o OpScan 16 Installation Guide

Installing the OpScan Scanner Utilities

Use the following instructions for installing the OpScan Scanner Utilities

For OpScan 2/4/6/8 and 4ES Scanners:

- 1. Insert the **OpScan Scanner Utilities** CD-ROM into the CD-ROM drive of the computer.
- 2. Browse to your CD-ROM drive.
- 3. Double-click **setup.exe**.
- 4. Follow the on-screen instructions.
- 5. Click Finish.

For OpScan 10/15/21 Scanners:

- 1. See *Installing USB Adapter Software for Windows 7* located in the Digi directory on the OpScan Scanner Utilities CD for information on installing drivers and configuring COM ports.
- 2. See the "Installing Software" section of the *OpScan 10/15 Installation Guide* for information about installing the OpScan Scanner Utilities.

• For OpScan 16 Scanners:

See the "Installing Software" section of the *OpScan 16 Installation Guide* for information on installing the OpScan Scanner Utilities.

OpScan, Scantron and the logo are trademarks, in the U.S. and/or other countries, of Scantron Corporation.

Microsoft, Windows, Windows NT, and Windows Vista are either registered trademarks or trademarks of Microsoft Corporation in the United States and/or other countries.